


Figure 13. Visual Renderings

LM_shippingCenter



Linda Mar shopping center

lindaMar_02



Linda Mar beach parking lot

vasslerRd



Vassler road

Figure 14. Vegetation Communities




Figure 15. Potential Wildlife Movement Corridors




Figure 16. Potential Special Status Species Habitat Map







Figure 17. Heritage Trees



-  Heritage tree to remain
-  Heritage tree to be removed
-  New replacement tree (Aesculus californica)

Source: TERRA FIRMA, Engineering-Surveying Land
 Planning, March 2007
 Map: TRA, May 2007




Figure 18. Biological Constraints





Figure 19. Mitigated Alternative Design for Lot 11



Figure 21. Local Geologic Map



EXPLANATION

- Landslide, arrows indicate direction of movement
 - Bedding Strike and Dip 45
 - Jointing Strike and Dip 60
 - Approximate Geologic Contact, queried where uncertain
 - Erosion Gully
 - Cutslope
 - Qaf** Artificial Fill
 - Qc** Colluvium
 - fs** Franciscan Assemblage, Sandstone
 - fg** Franciscan Assemblage, Greenstone
 - fsr** Franciscan Assemblage, Sheared Rock
- BASE: Overall Site Grading Plan, prepared by PKM, Inc., June 8, 2006

Scale: 1" = 300 feet

Figure 22. San Francisco Bay Area Fault Map

